







# 0403






[cm]  
v013  
09.05.2023  
K.M.







play  
Vinci
















**E37**  
K2,K3




[cm]




3,5h




play  
**Vinci**



403  
x1




995104  
x1




044110  
x2

K1,K2




042109  
x1

K3




042189  
x1

K1,K2




042127  
x1

K3




042188  
x1

K1,K2



992108  
x1

K3



992136  
x1

K1,K2




992107  
x1

K3



992135  
x1

K1,K2



042126  
x1

K3



042187  
x1

K1,K2



993118  
x1


K2, K3



B231  
x1


| ST/INOX |             | PLAYWOOD |      | HPL |      |
|---------|-------------|----------|------|-----|------|
| 1x      | E40         | 1x       | PS33 | 1x  | PH33 |
| 1x      | E48         |          |      |     |      |
| 3x      | E1          |          |      |     |      |
| 2x      | E71         |          |      |     |      |
| 1x      | E37 (K2 K3) |          |      |     |      |
| 2x      | E88 (K2)    |          |      |     |      |
| 1x      | E175 (K2)   |          |      |     |      |

K1




1x E40


K2



1x E175




E1




K2


2x E88




1x E71



E1



1x PS33 ○ PH33






1x E48





[cm]

play  
vinci



V001



[cm]

vinici play